

## BRANDYWINE SHAD 2020 WILMINGTON, DE.

## DAMS 3, 4, AND 6 REMOVAL



DRAWING LIST				
SHEET NO.	SHEET DESCRIPTION	DATE	REVISION	STATUS
D3-01	DAM #3, OVERALL EXISTING CONDITIONS	5-26-20	-	CLIENT REVIEW
D3-02	DAM #3, OVERALL PROPOSED CONDITIONS	5-26-20	-	CLIENT REVIEW
D3-03	DAM #3, PROFILES AND SECTIONS	5-26-20	-	CLIENT REVIEW
D4-01	DAM #4, OVERALL EXISTING CONDITIONS	5-26-20	-	CLIENT REVIEW
D4-02	DAM #4, OVERALL PROPOSED CONDITIONS	5-26-20	-	CLIENT REVIEW
D4-03	DAM #4, PROFILES AND SECTIONS	5-26-20	-	CLIENT REVIEW
D6-01	DAM #6, OVERALL EXISTING CONDITIONS	5-26-20	-	CLIENT REVIEW
D6-02	DAM #6, OVERALL PROPOSED CONDITIONS	5-26-20	-	CLIENT REVIEW
D6-03	DAM #6, PROFILES AND SECTIONS	5-26-20	-	CLIENT REVIEW






Kleinschmidt




CLIENT REVIEW
NOT FOR CONSTRUCTION
5-26-20

PRINTED:








PROPOSED DAM 3 CROSS SECTION


NOTES:

1. BREACH SIDE SLOPES TO BE 3:1 OR PER ENGINEER FIELD DIRECTION.

2. ESTIMATED MINIMUM BREACH WIDTH AT BREACH INVERT: 51 FEET




EXISTING DAM 3 & 4 PROFILE




PROPOSED DAM 3 & 4 PROFILE


SCALE IN FEET




NOTES:
1. CROSS SECTION AND PROFILE IMAGES WERE PROVIDED BY
THE UNIVERSITY OF DELAWARE.











NOTES:
1. BREACH SIDE SLOPES TO BE 3:1 OR PER ENGINEER FIELD DIRECTION.
2. ESTIMATED MINIMUM BREACH WIDTH AT BREACH INVERT: 50 FEET


PROPOSED DAM 4 CROSS SECTION



EXISTING DAM 3 & 4 PROFILE



PROPOSED DAM 3 & 4 PROFILE



NOTES:
1. CROSS SECTION AND PROFILE IMAGES WERE PROVIDED BY THE UNIVERSITY OF DELAWARE.

30 0 30 60 SCALE IN FEET

